

Construction Storm Water Inspection-10/18/05
Carlsbad Municipal Golf Course, WDID# 937C337203
Carlsbad, San Diego County



Photo 1
Mass Grading Operations (Facing North)



Photo 2
Example of Inadequate BMPs & Evidence of Sediment Discharges Under Silt Fence
(Facing East on College)

Construction Storm Water Inspection-10/18/05
Carlsbad Municipal Golf Course, WDID# 937C337203
Carlsbad, San Diego County



Photo 3
Example No Erosion Control on Exterior Slopes (Facing Northeast on College Ave)



Photo 4
Uncovered Slopes On Palomar Airport Road (Facing East)

Construction Storm Water Inspection-10/18/05
Carlsbad Municipal Golf Course, WDID# 937C337203
Carlsbad, San Diego County



Photo 5
Plastic Spillway For Sediment Trap (Facing Southeast)



Photo 6
Example of Incorrect Silt Fence Installation (Not Trenched In)